

TEST REPORT

on

Shear Wall Test On Sing Walls

for


SINGHOME COMPANY

McCleary, Washington

by

Prof. William M. Miller and Vince Chaijaroen

October 4th, 2002



SHEAR WALL TESTS ON SING – WALLS

By
William M. Miller

INTRODUCTION

In June of this year 2002 Dr. John Stanton, Director of the Civil Engineering Structural Testing Laboratory, engaged in contract with Mr. Peter Sing, President of the Singhome Company, McCleary, Washington, for the purpose of testing four shear walls constructed from “Sing logs”. Both the logs and the walls are yet to be described. These walls were tested under the control of Mr. Vince Chaijaroen, Engineering Technician and Lab Coordinator between the dates of July 17 and Aug. 14. Present for the first test (Wall No. I) were Designer Terry Sparks of Terry Designs in Redmond, WA., Mr. Richard Rock, P.E., of Rock Engineering, Port Orchard, Wash., and the writer, Prof. William M. Miller, P.E. and Emeritus Faculty, Dept. of Civil Engineering, Univ. of Washington. Present for the third test (which happened to be on Wall No, IV) were Mr. Tim Tyler, City of Everett Building Official, and Mr. Steven M. Miller, P.E., Associate Engineer, Building Division, Dept. of Public Works, Everett.

BACKGROUND

Sing logs begin with the sawing of small logs (see Fig. I-A).




FIG. I

APPARATUS AND INSTRUMENTATION

A photograph of the loading rack, with one of the walls in place, is shown in Plate I.



Plate 1

The rack contains an MTS hydraulic actuator, capable of a maximum load of 22 kips and a maximum displacement of 10 inches. Fixed into the ram was a load-cell, which was calibrated directly before the test. Also fixed to the ram was an LVDT electric extensometer. Uplift, resistance type, sensors were fixed at the corners of the base logs. Transfer of the actuator load to the shear wall was accomplished by initial delivery to a 4" by 10" steel channel placed on the flat. The pin to channel connection permitted the channel to rotate. Thus the channel connection to the wall sill produced a "rotation-free" end condition for the wall, in accordance with the standards prescribed in ASTM E72. Twenty-two rows of holes (four per row), 7/16 in diameter, provided for lag bolting to the top sill of the wall. Forty-six bolts, 3/8" by 2", were driven. To assist in the preclusion of wall slide in the rack, steel blocks were fixed to the rack base such that they butted up to each end of the base log. The rack was oriented in a north – south direction. All of the circuitry was completed at a monitor station located directly to the east of the wall and rack.

Data acquisition at the console consisted of load cell, LVDT (Linear Variable Differential Transformer) and uplift sensory readout on oscilloscope and computer screens. Data storage was accomplished with a HP Datalogger which gathered format data in an EXCEL type file.

ORIENTATION-SIGN CONVENTION-LOADING PROCEDURE

Established sign convention is as follows: A push on the wall is positive. A displacement from zero to the north is positive. Conversely, a pull on the wall is negative. A displacement from zero to the south is negative.

The loading procedure was of a static, complete reversal form. For pre-determined displacements, resultant lateral loads were read. The maximum displacement for the first cycle was arbitrarily established at plus and minus 0.10". Each cycle consistently began with a pull to the south. At a displacement of -0.10", the load was observed, then, the displacement was returned to a complete stop at zero. Next came the compressive half of the "ONE-TENTH" cycle, with a stop at +0.10"; then, a return to zero.

Maximum displacements for each cycle were chosen to increase by successive increments of 0.10". Thus the test continued on up to the condition associated with ultimate load. A sample plot is shown in Fig. III. This figure essentially summarizes the orientation and sign convention. Note that the figure arbitrarily illustrates the so-called "FOUR-TENTHS" cycle. The plot is randomly sketched in, purely for illustration. In the computer graphs to be presently reported, the limiting displacements will generally be within plus or minus 0.02" of the ideal maximum displacements desired. Accurate limiting loads will also accompany the more accurate limiting displacements. Less accurate limiting loads and displacements were recorded on a running, hand-held log sheet for each cycle in each test. These sheets are included in the appendix of this report. The numbers therein were hastily abstracted from rapidly changing screen readouts and can only be considered to be approximate.

SHEAR WALL NO. I

Plate I shows Shear Wall I in place. Figure II shows its dimensions. Also, it indicates the important features. The wall is characterized by tie rods that extend only through the base log. Four 5/8" diameter "All-thread" anchor rods complete the tie-down. Four couplings directly below the sole plate were snuggled up, mainly for the purpose of holding things together during wall fabrication and transport. Once the wall was seated on the base of the rack,





FIG. III

extension lengths of rods were required to complete the tie to steel channels on the rack. This detail is shown in Fig. IV. Also shown in this figure is a detail of the construction at the ends of the base log. Two, Douglas fir glued-in spacers, at 1 1/2" by 11" by 9 1/2", provided bearing parallel-to-grain for a 1/2" by 3" by 11" steel plate. The All-thread was then topped off with nut and washer. Four wood screws were additionally driven horizontally on each side of the base log. A photo of this connection is shown in Plate II.



Plate 2

Glue adhesive and Olympic "Oly-Log" log home fasteners (or equivalent) must necessarily take the place of the tie-rods in providing for tensile loading in the logs above the tie rod ends. They are also shown in Fig. IV. "Oly-Logs are also commonly referred to as "OlyScrews"



They are 12" long. Further facts about these fasteners can be found in the appendix of this report. The glue along the tongue and groove interfaces was "Tight-bond", a water soluble, "user-friendly" product. It is generally laid down with a caulking gun, to produce two "field" glue lines (1/2" wide) along each plank of the base log.

Of considerable importance is to note that, in Wall I, two Oly-Screws for each plank were driven into the first eleven inches of the logs, at each end. Two more (one on each plank) were placed at the longitudinal center of each T&G interface. Thus, a major feature of Wall I is “ten - Oly- Screw per interface” throughout the wall.

Two other tie-down All-thread rods were symmetrically spaced along the base log. Figure II shows this feature. These, however, were capped off with doubled-up ¼” by 2” by 5” steel plates that spanned the two planks thus creating a condition of bearing perpendicular to the grain. The plates sat in a mitered insert.

TEST RESULTS: (Appendix A) Graph I shows an array of computer plots for a number of displacement cycles. Graph II shows an arbitrarily selected plot of the “FIVE TENTHS” displacement cycle. Most important is the “1.3 - INCH” cycle since, in this, structural failure occurred. This is shown in Graph III. Note that, at a displacement of +1.292”, the ultimate lateral load was +7.292kips. At this point an open crack appeared at the south end of the T&G interface of the base log. For the first half of the following “1.4 - INCH” cycle, at a -1.394” displacement, with a pull of -5.969 kips, a similar interface separation occurred at the north corner. For the second half of this cycle the compressive load dropped from +7.292kips to +6.65kips (see Graph IV). Failure was tensile, both in the adhesive and the Oly- Screws. A photo of the failed section on the south end is shown in Plate III. Plate IV shows failure conditions on the north corner. Two of the Oly-Screws on the north end fractured. One fractured on the south end. The remaining end Oly Screws failed either in pull-out or pull-through.



Plate 3



Plate 4

SHEAR WALL NO. III

Failure of the interface of Wall I revealed a defect. The adhesive appeared to be unusually soft and pliable. It had apparently not fully cured. Further investigation revealed the fact that the interface “field” seams could very well have been subjected to damaging stresses in the process of handling and transport. Wall I was constructed at the owner’s Mill on its side. It was eventually lifted to a vertical position then laid flat on a trailer bed. Upon arrival at the laboratory, it was again lifted to vertical, stored flat, then raised to vertical once more before being placed on the loading rack. High normal stresses due to bending could very well have caused preliminary damage.

Wall No. III was constructed to enhance the performance of the glue. It had identical dimensions and features to those of Wall I, except that careful attention was given to maximizing bond surface along the field seams. Also, it was constructed vertically in a temporary rack set up on the trailer bed for which it was to be transferred. In the laboratory it was also kept vertical at all times. Two weeks of drying time was prescribed. Furthermore, the number of Oly-Screws per interface was increased to 16. Six screws were placed within the first 11” of each log, as opposed to the four in Wall I. Also, four more (instead of two) were symmetrically spaced at interior longitudinal stations.

TEST RESULTS: Graph V is an array of a number of the smaller displacement cycles, provided only for casual observance. The most important cycles follow individually in Graphs VI through IX. Graph VI shows the “EIGHT-TENTHS cycle where, during the second half of the cycle, an ultimate compressive load of +10.586 kips produced failure. A longitudinal crack, ¼” wide and 27” long opened up in the

south end of the east plank of the base log. The crack was just below the gimlet points of the Oly-screws (three inches down from the T&G interface). Upon investigating the corresponding west plank, a similar split was observed. The compressive load rapidly dropped to +6kips Plate V shows a photo of the splitting.



Plate 5

In the subsequent “NINE-TENTHS” cycle (see Graph VII), the maximum tensile force rose to -11.193 kips. The maximum compressive force recovered modestly from $+6$ kips to $+8.185$ kips. During the first half of this cycle there was the first evidence of a split in the north end of the base log.

For the “ONE-INCH CYCLE” (see GRAPH VIII), through the first half (tensile), the load bearing capacity of the wall continued to rise, going from -11.193 kips to -11.745 kips. Meanwhile the split in the north end continued to propagate. It was only after completion of the tensile half of the “1.10 - INCH” cycle that there was a fall-off of the maximum tensile load from -11.745 kips to minus 11.095 kips (see Graph IX).

The modifications to Wall III served to bolster the performance of the base log T&G interface. It remained in tack throughout the test. Also, the strength of the wall improved over that of Wall 1 by about 3.3 kips. What the modifications did was to “fix the weakest link”, only to move the weakness to another (but not far away) level. There was a combined failure. First, the upper three inches of the 2 ” by 12 ” spacer glued surfaces failed in shear. This left only the two base planks to take the tension. The wood failed in tension perpendicular to the grain. The same kind of failure occurred at both ends. Close-ups of the Wall III failures are shown in Plates VI and VII



Plate 6



Plate 7

SHEAR WALL NO. II

Shear Wall No. II was quite different from walls I and III. While it was the same size and the same species, it was characterized by end tie-down rods that extended vertically from the bottom of the rack channels to the top of the wall. Figure II shows true dimensions and exacting details of this wall. Because room was needed between the top channel on the rack and the top of the wall, for the capping of the rods with nuts, the top log was necessarily shortened 6" on each end. This wall obviously did not require the base log end bearing surfaces required in Walls I and III. The spacers in the base log were the typical doubled up 2 by 4's placed 6" in from both ends, plus others of the same placed longitudinally about every 2'. With the exception of the top two logs, all of the other logs in the wall were made the same. The second log down from the top now necessarily contained the bearing blocking. A $\frac{3}{4}$ " by 6" by 8" steel plate rested on two glued-in 1 $\frac{1}{2}$ " by 6" by 9 $\frac{1}{2}$ " blocks. The wood was subjected to compression, part in parallel and part in perpendicular to the grain. Intermediate tie-down rods were identical to those of Walls I and III. Each T&G interface contained ten Oly-Screws spaced the same as they were in Wall I. Plate VIII shows Wall II set up in the rack and ready to go.



Plate 8

TEST RESULTS: From the outset, this wall exhibited some strange behavior. Upon loading, there was the sound from sliding wood surfaces, which amplified with each successive cycle. Successive cycles in the lower increment range produced small visible relative horizontal displacements along the T&G interfaces. The wall was behaving somewhat like a deck of well-used cards. Upon reaching the end of the “NINE-TENTHS” cycle, the wall produced the sound of a loud crack. The third interface from the base of the rack developed an instantaneous longitudinal relative displacement of about ½” (see Plate IX, showing the shift to the north). The maximum compressive load at the end of this cycle was +6.730kips. This is shown in Graph X). Graph XI of the “ONE-INCH” cycle shows the “dropping off” of the “ultimate” loads that were experienced through each half of the “NINE-TENTHS” cycle. Shear failure was obviously in the adhesive along the interface.



Plate 9

An investigation into this strange behavior revealed the fact that this wall, which was fabricated at the Sing Mill, contained little (if any) glue along the field seams. The employee reported that he placed, at best, a thin layer of adhesive only along the tongue surfaces of each log. This shortage of bond surface, along with relatively minimal curing pressure provided by the ten Oly-Screws, proved to be a disaster. Furthermore, this wall, in the process of temporary storage and transportation, was handled in the same way as was Wall I. If the field seams developed any bond strength at all, it could have been destroyed, in part, through handling.

When this test was completed, the process of returning the actuator to its zero position was such as to return this “stack of cards” to its original orderly vertical pile. Aside from some local wood crushing next to the Oly-Screws, the wall was undamaged. As an aftermath, the writer took the opportunity to interject an experiment. Using a bonding agent named “MOR-AD-M513”, a quick drying, insoluble adhesive, the T&G field seams were caulked and allowed to cure for three days. The procedure could not accurately be described as “injection gluing”, but it was intended to certainly suggest a potential procedure for “field post gluing”.

This modified wall was subjected to a simple monotonic (one direction) pull, the results of which are shown in Graph XII. It shows an ultimate load of minus 10.760kips an increase of about 4kips over its “no-glue” counterpart. Again the sliding type failure occurred along the third interface up from the bottom of the wall.

SHEAR WALL NO. IV

This wall was a replication of Wall II in almost every way. Size, species, dimensions, number of Oly-Screws per T&G interface and all four tie-downs were exactly the same. The major difference however was in the gluing of the T&G surfaces. The adhesive remained the same, namely MOR-AD M-513, but it was carefully distributed over the interface surfaces. Also, this wall was constructed and allowed to cure in the loading rack.

TEST RESULTS: The wall responded quietly. At the end of the “SIX-TENTHS” cycle the load fell off somewhat (about 2 kips below the previous cycle). Observers discovered that the north block on the frame base had slid about 3/8” to the north. The block (and the wall) was returned to its original position, all tie-downs and the block were re-tightened; then the test was continued. The wall behaved well, developing continuously increasing load bearing capability, on up to, and through, the “1.4 - INCH” cycle. This cycle is shown in Graph XIII. During the first half of the “1.5 - INCH” cycle (shown in Graph XIV), under a load of -17.482kips, there was a loud “pop” from the north end and the load dropped off to about -9kips. On completion of this cycle the peak compressive load was +16.747kips. This was accompanied by another “pop”, now coming from the south end.

Observation of the wall at this point revealed similar developments at both ends of the base log. The sole 2” by 8” crushed to produce the shape of an arch along its top surface. Planks on both sides of the log began to rotate outward causing the wall to produce a local “bulge” buckle. This in turn caused a tension failure in the glue surface between a plank and a 2” by 4” spacer. This pair of failures is shown first in Plate X (south end) and next in Plate XI (north end).



Plate 10



Plate 11

Of interesting note is the fact that the wall, under the subsequent displacement cycle (“1.6 INCH) exhibited renewed load bearing capability (see Graph XV). The cycling continued. During the first half of the 1.7 INCH cycle (see Graph XVI), at a load of -10.636 kips, there was a snapping of steel. The nut on the north tie-rod, under the rack channel, sheared through the washer.

Some repairs were made on the tie-downs. Replacement nuts, along with doubled-up washers, were fitted to all four, and a final cycle was begun. During the first half of the “1.8 INCH “ cycle (see Graph XVII), at a displacement of -1.756 ” and an absolute ultimate load of -20.134 kips, collectively catastrophic failure was reached. Local buckle was observed in the first two logs in the lower corners. This was accompanied by a stripping of the thread at the top of the south tie - down rod. Throughout all of this, the properly placed adhesive along the field seams behaved extremely well. There was no evidence of failure it that glue, either in shear or in tension. Plate XII is an exhibit of the damaged tie-downs.




Plate 12

UPLIFT

Uplift, associated with tendency to overturn, was monitored throughout the testing. It was minimal. Maximum corner uplifts for each corner, for each wall are reported below.

SHEAR WALL	SOUTH CORNER	NORTH CORNER
I	0.167"	0.136"
II	0.200"	0.123"
III	0.003"	0.070"
IV	0.481"	0.407"

In general, the end tie-downs, in all cases, performed quite well in bearing. The bearing surface areas that were provided proved to be adequate.

CONCLUSION

A concluding summary table is shown in TABLE I.

WALL NO.	BRIEF DESCRIPTION	END TIE-DOWNS	ADHESIVE IN T&G INTER-FACE	POSITIONS OF OLY-SCREWS	NR. OF OLY-SCREWS	WALL DISP. (INCHES)	ULT. SHEAR LOAD (KIPS)	ULT. STRIKE ELEM. (KIPS)
I	STANDARD	5" DIA. ONLY THIRD BASE LOG	SOLUBLE TIGHT-BOND (NOT FULLY CURED)	4 AT EACH END; TWO INTERMEDIATE	10	1.292"	7.292	931
III	REPLICATION OF WALL I; BETTER GLUING-MORE OLY	SAME AS ABOVE	TIGHT-BOND (CURED FOR TWO WEEKS)	6 AT EACH END; FOUR INTERMEDIATE	16	0.786"	10.586	1352
II	THROUGH END TIE-DOWNS NO GLUE	8' LONG; FROM BASE FRAME TO TOP OF WALL	LITTLE OR NONE	4 AT EACH END; TWO INTERMEDIATE	10	0.898"	6.730	860
II	SAME AS ABOVE; EXCEPT POST GLUED	SAME AS ABOVE	POST GLUED. "MOR-AD-M-513"	SAME AS ABOVE	10	1.002"	10.760	1374
IV	REPLICATION OF II EXCEPT PRE-GLUED	SAME AS ABOVE	SAME AS ABOVE	SAME AS ABOVE	10	1.469"	17.482	2233

TABLE I - SUMMARY OF RESULTS

The reported “Ultimate Loads” for each wall are those that related to the first sign of distress, even though the wall may have developed additional strength in subsequent cycles. Reported Ultimate Shear Flows were derived by multiplying the listed Ultimate Loads by 1000/7.83.

The reader should be reminded at this point that, because of the “rotation-free” connecting feature of the loading channel at the top of the wall, The wall behaved much more like an ideal cantilever beam than one having “rotation fixity” at both ends. Field conditions for shear walls are usually such that gravity loads are delivered from second stories, and second story floors are quite stiff, suggesting that the more realistic analogized beam model should develop equal moments at both top and bottom. These moments would only be half as much as that which develops at the fixed base of the pure cantilever. The point to be made is that the “pure cantilever” shear wall test (specified in ASTM E72) is conservative. This factor must be kept in the mind of the structural engineer, should he desire to establish an “allowable shear flow” by projecting the findings of these tests into his individual designs.

William M. Miller P.E.

Client Information:

SINGHOME COMPANY

162 Summit Road N.


McCleary, WA 98557

Tel:(360) 495-3577 Fax:(360) 495-4585


e-mail: singhomes@techline.com

Appendix A


Graphs




Graph I




Graph II




Graph III




Graph IV




Graph V




Graph VI




Graph VII




Graph VIII




Graph IX




Graph X




Graph XI




Graph XII




Graph XIII



Graph XIV




Graph XV



Graph XVI

Wall 4 at 1.8"



Graph XVII

Graph XVII

Appendix B

Miscellaneous

LOG SHEET: SHEAR WALL NO. I

CYCLE RANGE (INCHES)	PULL TO SOUTH		PUSH TO NORTH		COMMENTS
	MAXIMUM NEG. DIS- PLACEMENT (INCHES)	MAXIMUM NEG. LOAD (KIPS)	MAXIMUM POS. DIS- PLACEMENT (INCHES)	MAXIMUM POS. LOAD (KIPS)	
0.10	0.089	1.308	0.060	0.931	
0.20	0.198	1.843	0.222	1.928	
0.30	0.224	3.15	0.295	3.14	
0.40	0.389	4.000	0.40	4.7	
0.50	0.469	4.52	0.475	5.37	
0.60	0.584	5.36	0.579	4.8	
0.70	0.677	4.8	0.672	5.92	
0.80	0.796	5.74	0.776	6.23	
0.90	0.884	5.90	0.855	6.47	
1.00	0.985	6.25	0.988	6.93	SPLITS IN BOTH SIDES, SOUTH END OF BASE LOG, RUNNING ALONG T & G INTERFACE. (1/2" WIDE)
1.10	1.063	6.02	1.065	6.66	
1.20	1.165	6.18	1.162	6.93	
1.30	1.27	6.21	1.258	7.25*	
1.40	1.358	5.9	1.36	6.65	
1.50	1.468	5.12	1.471	6.70	
1.60					
1.70					
1.80					
1.90					

DATE: JULY 17, 2002

LOG SHEET: SHEAR WALL NO. II

CYCLE RANGE (INCHES)	PULL TO SOUTH		PUSH TO NORTH		COMMENTS
	MAXIMUM NEG. DIS- PLACEMENT (INCHES)	MAXIMUM NEG. LOAD (KIPS)	MAXIMUM POS. DIS- PLACEMENT (INCHES)	MAXIMUM POS. LOAD (KIPS)	
0.10	0.094	0.946	0.086	1.00	INITIAL CREAKING
0.20	0.202	3.29	0.186	2.437	
0.30	0.297	3.30	0.280	3.41	
0.40	0.380	4.16	0.392	4.33	MORE CREAKING
0.50	0.481	5.04	0.490	5.07	
0.60	0.578	5.60	0.588	5.71	EVIDENCE OF SLIDING LOGS
0.70	0.700	6.47	0.691	6.41	
0.80	0.771	6.82	0.802	6.52	
0.90	0.881	6.89	0.898	6.71	EXCESSIVE SLIP ALONG THIRD SEAM UP FROM BASE
1.00	0.971	5.68	0.857	5.82	
1.10	1.067	5.74	1.07	5.21	
1.20	1.16	4.07	1.18	4.57	
1.30	1.46	3.2	1.48	4.55	PHOTO TAKEN
1.40					
1.50					
1.60					NEGLECTIBLE UPLIFT THROUGH- OUT.
1.70					
1.80					
1.90					

DATE: JULY 18, 02

LOG SHEET: SHEAR WALL NO. II

CYCLE RANGE (INCHES)	PULL TO SOUTH		PUSH TO NORTH		COMMENTS
	MAXIMUM NEG. DIS- PLACEMENT (INCHES)	MAXIMUM NEG. LOAD (KIPS)	MAXIMUM POS. DIS- PLACEMENT (INCHES)	MAXIMUM POS. LOAD (KIPS)	
0.10					MONOTONIC TEST (PULL TO SOUTH) (SINGLE RUN) GREATEST SLIP FAIL- URE WAS ALONG 3RD. SEAM UP FROM BASE
0.20					
0.30					
0.40					
0.50					
0.60					
0.70					
0.80					
0.90					
1.00	1.005	10.68			
1.10					
1.20					
1.30					
1.40					
1.50					
1.60					
1.70					
1.80					
1.90					

DATE: JULY 23, 02

LOG SHEET: SHEAR WALL NO. III

CYCLE RANGE (INCHES)	PULL TO SOUTH		PUSH TO NORTH		COMMENTS
	MAXIMUM NEG. DIS- PLACEMENT (INCHES)	MAXIMUM NEG. LOAD (KIPS)	MAXIMUM POS. DIS- PLACEMENT (INCHES)	MAXIMUM POS. LOAD (KIPS)	
0.10	0.10	1.74	0.090	1.42	
0.20	0.198	3.42	0.198	3.72	
0.30	0.239	4.72	0.288	5.42	
0.40	0.389	5.42	0.388	6.92	
0.50	0.492	7.24	0.489	7.99	
0.60	0.589	8.52	0.595	9.23	
0.70	0.701	9.8	0.705	10.26	
0.80	0.794	10.55	0.781	10.57	TENSION FAILURE AT SOUTH END CORNER, 27" CRACK
0.90	0.880	11.19	0.864	8.30	
1.00	0.996	11.74	0.988	8.92	OPENING OF A SPLIT IN NORTH END BASE LOG.
1.10	1.08	11.09	1.07	8.68	
1.20					
1.30					
1.40					SPLIT NOW 1/2" WIDE 31" LONG.
1.50					
1.60					
1.70					
1.80					
1.90					

DATE: AUG. 14, 02

LOG SHEET: SHEAR WALL NO. IV

CYCLE RANGE (INCHES)	PULL TO SOUTH		PUSH TO NORTH		COMMENTS
	MAXIMUM NEG. DIS- PLACEMENT (INCHES)	MAXIMUM NEG. LOAD (KIPS)	MAXIMUM POS. DIS- PLACEMENT (INCHES)	MAXIMUM POS. LOAD (KIPS)	
0.10	0.089	1.574	0.089	1.00	
0.20	0.186	4.09	0.185	3.72	
0.30	0.289	5.80	0.281	5.81	
0.40	0.398	7.92	0.392	7.30	
0.50	0.475	9.13	0.471	8.41	DETECTED SLIDING IN BACK. SITU- ATION RE- PAIRED.
0.60	0.563	10.34	0.559	6.52	
0.70	0.667	11.52	0.658	8.00	
0.80	0.775	13.35	0.67	12.6	
0.90	0.862	13.8	0.849	13.16	LOUD POP FROM NORTH END. THE 17.36 KIP LOAD DROPPED OFF TO 8.8 KIPS
1.00	0.976	14.84	0.967	14.1	
1.10	1.06	15.5	1.05	14.7	
1.20	1.169	16.25	1.165	15.48	
1.30	1.266	16.80	1.26	15.92	
1.40	1.36	17.01	1.36	16.36	
1.50	1.46	17.36	1.436	16.14	← LOUD POP FROM SOUTH END.
1.60	1.563	11.76	1.57	17.03	
1.70	1.68	10.00	←	←	SNAPPING OF STEEL ROPE. NORTH TIE-ROD NOT PULLED THRU WASHER AT BASE.
1.80	1.691	20.52	1.58	16.9	
1.90					

DATE: AUG. 13, 02

LOCAL BULGE BUCKLES IN FIRST TWO LOGS IN LOWER CORNERS, BOTH ENDS, ALSO, STRIPPING OF THREADS AT THE TOP OF THE SOUTH TIE-DOWN ROD.



REPORT
ETL TESTING LABORATORIES, INC.

INDUSTRIAL PARK

CORTLAND, NEW YORK 13045

Order No. 81419-481

Date: February 9, 1994

REPORT NO. 536848

TEST OF OLYMPIC "OLY-LOG"
LOG HOME FASTENERS

RENDERED TO

OLYMPIC MANUFACTURING GROUP, INC.
PO BOX 508
AGAWAM, MA 01001

Introduction

This report presents the results of examination and test of the above log home fasteners.

Procedure

Testing was conducted to the test protocol for testing Olympic "Oly-Log" log home fasteners as submitted by the client, which referenced sections of ASTM designation: D1761-88, standard test methods for mechanical fasteners in wood.

Description of Materials

Oly-Log (Black Finish)
5/16-inch Hex Head
7.5 TPI
Gimlet Point
8-inches Long
2-inches of Threads
.190-inch Shank Diameter

Panel Fastener (Red Finish)
Flat Head #3 Square Drive
10 TPI
Single Edge Drill Point
8-inches Long
2-inches of Threads
.190-inch Shank Diameter

An independent organization testing for safety, performance, and certification.

All services undertaken subject to the following general policy: Reports are submitted for exclusive use of the clients to whom they are addressed. Their significance is subject to the adequacy and representative character of the samples and to the comprehensiveness of the tests, examinations or surveys made. No quotations from reports or use of ETL's name is

INSTALLS MUCH FASTER/EASIER THAN LAGS & SPIKES
 -SAVES TIME/FATIGUE
 -LOWEST INSTALLED COST

REQUIRES NO PRE-DRILLING
 -ELIMINATES ON-SITE PREDRILLING
 -ELIMINATES MANUFACTURING DRILL STATIONS

COUNTERSINKS INTO LOG
 -ALLOWS LOGS TO SETTLE

ALLOWS LOG S TO SETTLE
 -COUNTERSINKS
 -2" THREAD IS ONLY EMBEDDED INTO BOTTOM LOG
 -MAJOR DIAM OF THREADS LARGER THAN SHANK DIAMETER, THEREFORE, TOP LOG ABLE TO MOVE FREELY


DRAWS DOWN WARPED LOGS

REMOVABLE/REUSABLE

ELIMINATES JARRING AND DAMAGE A SLEDGE HAMMER CAN CREATE

**ULTRA COAT
 (HIGHLY CORROSION RESISTANT)**

**ANTI-FRICTION CLEAR COAT
 (TEFLON ADDS LUBRICITY)**



Report No. 536848

Test Specimens (6 x 6 x 12-inches)

The wood blocks were of Northern White Cedar (Group D) and Ponderosa Pine (Group C) and was cut from graded "Number 1" lumber. Prior to being shipped to ETL Testing Laboratory, Inc., located in Cortland, New York, the wood was conditioned in an oven and the moisture content determined by the client.

Withdrawal Test

Fasteners were inserted into the wood perpendicular to the grain in accordance with the manufacturers specification using the tool recommended and supplied by the client. The installation of the fasteners was provided by a representative of Olympic Manufacturing, Inc., Mr. Stan Choiniere. The point of each fastener was embedded in the holding piece to a minimum depth of 2 inches. (The length of the threaded section of the fastener) The uniform load rate of withdrawal was 0.10-in/min. throughout the test.

Results

Reference Table 1 and Appendix A.

Shear Test #1

The test specimen was assembled by overlapping the members by 4-inches, thus forming a test specimen 20-inches long. The fastener was inserted at the center of the width of the blocks and the center of the overlap (2-inches from the overlapping end of the members) The installation of the fasteners was provided by a representative of Olympic Manufacturing, Inc., Mr. Stan Choiniere. The uniform load rate of shear was 0.10-in/min. throughout the test.

Results

Reference Table 2 and Appendix B.

Lateral Test

The fasteners were inserted perpendicular to the grain until the head of the fasteners engaged the top of the block exposing 2-inches of threads thru the bottom. The fasteners were installed by a representative of Olympic Manufacturing, Inc., Mr. Stan Choiniere. A force was applied to the threads to pull the head of the fasteners thru the blocks. The uniform load rate throughout the test was 0.10-in/min.

Checked by: *SR*

TABLE 1
WITHDRAWAL LOAD TEST RESULTS

TEST NUMBER	OLYLOG IN PINE	OLYLOG IN CEDAR	PANEL FASTNER IN PINE	PANEL FASTNER IN CEDAR
UNITS	POUNDS	POUNDS	POUNDS	POUNDS
1	1092.5	1095.0	1355.0	1290.0
2	1600.0	1350.0	1257.5	1317.5
3	1317.0	1345.0	1500.0	1207.5
4	1055.0	1238.0	1305.0	1117.5
5	1690.0	1140.0	1460.0	1050.0
6	1525.0	1650.0	1305.0	1200.0
7	1580.0	1045.0	2225.0 *B*	1015.0
8	1537.5	825.0 *A*	1305.0	1170.0
9	1587.5	1290.0	1400.0	1280.0
10	1532.5	990.0	1275.0	1460.0
11	1315.0	1000.0	1580.0	1265.0
12	1520.0	1260.0	1367.5	1260.0
13	1510.0	1300.0	1505.0	1230.0
14	1465.0	1390.0	1362.5	1260.0
15	1357.5	1120.0	1430.0	1042.5
16	1715.0	1225.0	1665.0	1055.0
17	1370.0	1365.0	1275.0	1165.0
18	1185.0	1147.5	1125.0	1145.0
19	1490.0	1110.0	1983.5	1170.0
20	1465.0	1230.0	1370.0	1845.0

NOTES:

- *A* : CEDAR BLOCK SPLIT FROM SCREW HOLE TO END OF BLOCK.
- *B* : SCREW HEAD BROKE OFF ABOVE SHOULDER.

**TABLE 2
SHEER TEST RESULTS**

TEST NUMBER	OLYLOG IN PINE	TRAVEL LENGTH	LENGTH & LOCATION OF BREAK	PANEL FASTNER IN CEDAR	TRAVEL LENGTH	LENGTH & LOCATION OF BREAK
UNITS	POUNDS	INCHES	INCHES	POUNDS	INCHES	INCHES
1	825.0	0.50	1.00	1065.0	0.88	1.00
2	755.0	0.50	0.50	1135.0	> 1.50	NO BREAK
3	825.0	0.63	0.75 *B*	825.0	0.50	0.75
4	1045.0	0.75	0.88	1200.0	0.38	0.88
5	870.0	0.63	1.13	1127.5	0.25	0.63
6	815.0	0.38	0.75	1040.0	> 1.50	NO BREAK
7	910.0	0.38	0.75 *B*	935.0	0.38	0.75
8	895.0	0.38	0.88	1085.0	0.63	0.88
9	1180.0	1.00	1.25	930.0	0.13	0.75
10	1135.0	0.75	1.00	1125.0	0.50	0.88
11	857.5	0.50	0.88	830.0	0.38	0.63
12	1220.0	0.75	0.75 *B*	1075.0	0.50	0.88
13	1000.0	0.50	0.88 *B*	1035.0	0.63	0.88
14	760.0	0.25	0.75	1345.0	0.50	1.13
15	845.0	0.50	0.75	825.0	0.38	0.75
16	620.0	0.38	0.75	870.0	0.50	0.75
17	760.0	0.38	0.88 *B*	1645.0	> 1.50	NO BREAK
18	940.0	1.00	1.00 *B*	1037.5	> 1.50	NO BREAK
19	1295.0	0.63	0.75	890.0	0.25	0.63 *B*
20	875.0	0.63	0.88	935.0	> 1.50	NO BREAK

NOTES:

A : ALL BREAKS ON SHANK UNLESS NOTED DIFFERENTLY.

B : SCREW BROKE ON THREADS AS SCREW PULLED OUT OF SECOND BLOCK.

**TABLE 3
LATERAL LOAD TEST RESULTS**

TEST NUMBER	OLYLOG IN PINE	PANEL FASTENER IN CEDAR
UNITS	POUNDS	POUNDS
1	1125.0	2750.0
2	1232.5	2250.0
3	2322.5	3175.0 **
4	982.5	1750.0
5	1290.0	2025.0

NOTES:

** : SCREW HEAD BROKE OFF AT SHANK / RADIUS INTERFACE.

**TABLE 4
BOLT STRENGTH TEST RESULTS**

TEST NUMBER	OLYLOG IN PINE	PANEL FASTENER IN CEDAR
UNITS	POUNDS	POUNDS
1	2500.0	2550.0
2	2600.0	0.0 **

NOTES:

** : UNABLE TO PERFORM / TEST FITURES STRETCHED.

**TABLE 5
SHEER TEST RESULT USING TWO SCREWS**

TEST NUMBER	OLYLOG IN PINE	TRAVEL LENGTH	LENGTH & LOCATION OF BREAK	LENGTH & LOCATION OF BREAK
UNITS	POUNDS	INCHES	INCHES	INCHES
1	1605.0	0.50	NO BREAK	0.75